



1 SCOPE

This document details the application of SOP 281 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
August 2002	1	David Naylor	Initial Issue 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
David Naylor Senior Project Engineer	Alastair Ferguson Section Head Engineering Support	Eric Leavy Engineering & Transmission Operations Manager



4 SOP DETAILS

TYPE : Cutler Hamer (Ottermill) type W-VAC Circuit Breaker

ORIGINATING REC : NEDL (Northern Electric)

DATE : 04/10/2001

NO. INSTALLED IN MANWEB: None

STATUS : Restriction: No access to rear of switchboard with Voltage Transformer Live.

REASON: Disruptive failure of Voltage Transformer as reported in DIN 2001/0087

UPDATE:

REMEDIAL ACTION: The restriction will be reviewed following an investigation and report by manufacturer.