



**1 SCOPE**

This document details the application of SOP 288 issued by the Electricity Association.

**2 ISSUE RECORD**

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

<b>Issue Date</b>	<b>Issue No</b>	<b>Author</b>	<b>Amendment Details</b>
August 2002	1	David Naylor	Initial Issue 2 Page Document

**3 ISSUE AUTHORITY**

<b>Author</b>	<b>Owner</b>	<b>Issue Authority</b>
David Naylor Senior Project Engineer	Alastair Ferguson Section Head Engineering Support	Eric Leavy Engineering & Transmission Operations Manager  .....



**4 SOP DETAILS**

**TYPE :** Reyrolle OB14 132kV circuit breaker

**ORIGINATING REC :** National Grid

**DATE :** 14/12/2001

**NO. INSTALLED IN MANWEB:** None.

**STATUS :** Restriction: For planned opening of the circuit breaker, a 30m risk management zone has been implemented, pending the findings of an incident investigation.

**REASON:** Breaker “blast tube” failed disruptively at Rayleigh Local sstn, DIN 2001/0109/00 refers. Incident investigation underway.

**UPDATE:**

**REMEDIAL ACTION:**