

1. SCOPE

This document details the application of SOP 298 issued by the Electricity Association.

2. ISSUE RECORD

This is a controlled maintained document.

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2002	1	D.W. Naylor	Initial issue 2 page document

3. ISSUE AUTHORITY

Author	Owner	Issue Authority
David Naylor Senior Project Engineer	Alastair Ferguson Section Head Engineering Support	Eric Leavy Engineering & Transmission Operations Manager

4. SOP DETAILS

TYPE : Cutler Hammer circuit breaker type W-VAC

ORIGINATING REC : NEDL (Northern Electric)

DATE : 21 October 2002

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND: 0

STATUS : Restriction: no access to rear of switchboard with voltage transformer live.

REASON: Disruptive failure of voltage transformer.

This SOP as created duplicates SOP 281.

UPDATE:

REMEDIAL ACTION: