



**1. SCOPE**

This document details the application of SOP 303 issued by the Electricity Association.

**2. ISSUE RECORD**

**This is a controlled maintained document.**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

<b>Issue Date</b>	<b>Issue No</b>	<b>Author</b>	<b>Amendment Details</b>
September 2003	1	D.W. Naylor	Initial issue 2 page document

**3. ISSUE AUTHORITY**

<b>Author</b>	<b>Owner</b>	<b>Issue Authority</b>
David Naylor Senior Project Engineer	Alastair Ferguson Section Head Engineering Support	Alastair Ferguson Section Head Engineering Support  .....

#### **4. SOP DETAILS**

**TYPE :** Lucy switchgear types:  
SFRMU, SF<sub>6</sub> ring main unit,  
SFS1E, SF<sub>6</sub> extensible switch fuse  
SFRMUE, SF<sub>6</sub> extensible ring main unit

**ORIGINATING DNO :** Defence Estates

**DATE :** 21 July 2003

**NO. INSTALLED IN POWER SYSTEMS NORTH:** 0  
**NO. INSTALLED IN POWER SYSTEMS SOUTH:** 0

**STATUS :** Ban on live operation.

**REASON:** Partial discharge activity within fuse chamber

**UPDATE:**

**REMEDIAL ACTION:** Operational restriction may be lifted after inspection and installation of a retro-fit kit available from W Lucy & Co.