

1. SCOPE

This document details the application of SOP 2008/0351/00 (Applicable to Tapchangers at all voltages above 11kV) issued by the Energy Networks Association.

2. ISSUE RECORD

This is a Reference document. The current version is held on the Energy Networks Intranet Document Library.

It is your responsibility to ensure you work to the current version.

Issue Date	Issue No	Author	Amendment Details
May 2008	1	Alastair Ferguson	Initial SOP Issue
June 2013	2	Alan MacGregor	Voltage Regulator addressed

3. ISSUE AUTHORITY

Author	Owner	Issue Authority
Alan MacGregor	Alastair Ferguson	Jim Sutherland
Lead Engineer, Technical Risk	Asset Risk Manager	Engineering Director
		JSallal

4. REVIEW

This is a Reference document which has a 5 year retention period after which a reminder will be issued to review and extend retention or archive.

5. DISTRIBUTION

This document is not part of a Manual maintained by Document Control and does not have a maintained distribution list.



6. SOP DETAILS

EQUIPMENT TYPE: ORIGINATING DNO	AEI Type ME 501 Tapchanger EDF Energy
DATE:	8 th May 2008
NUMBER INSTALLED IN ENERGY NETWORKS NORTH:	None
NUMBER INSTALLED IN ENERGY NETWORKS SOUTH:	None
REASON:	Issued following the fatality of a member of staff while hand cranking a tap-changer of the above type on a 132/11kV transformer.
STATUS IN INITIATING DNO:	Tap changers (at all voltages above 11kV) must not be operated by hand cranking with the transformer live. No work, or activities, will take place in the immediate vicinity of AEI ME501 Tap Changers.
SPEN APPLICATION:	Where manual tap change operations (or local electrical operation from the adjacent control cubicle) are required on primary (33/11/6.6kV) or grid transformers, these operations shall be carried out with the associated transformer de-energised.
	In all cases this shall be done with the agreement of the Control Engineer and any exceptions to this requirement shall be subject to the agreement of the OCC Manager.
	These requirements must be considered when investigating any tapchanger or associated control system fault.
	Automatic operation and operations from the substation control room or by telecontrol are unaffected by this restriction.
	[Safety Bulletin EXP-10-102 refers]
UPDATE:	For clarity, this SOP does not apply to 11kV automatic voltage regulators, both pole and ground mounted. However, any defect investigation on 11kV voltage regulators shall consider whether the unit could be deenergised before undertaking work.
REMEDIAL ACTION:	None