



## 1 SCOPE

This document details the application of SOP 4 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### **4 SOP DETAILS**

**TYPE:** Yorkshire IVI Mk4 O.S.

**ORGINATING REC:** Midlands Board

**DATE:** 24/8/78

**NO. INSTALLED IN MANWEB:**0

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** (Restriction) None on Manweb system.

**REASON:** Mk IV isolating contacts failed on fault.

**UPDATE:**

**REMEDIAL ACTION:** Replace contacts.