



1 SCOPE

This document details the application of SOP 26 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: GEC/English Electric T3 & T3/OF Cable Boxes

ORIGINATING REC: Yorkshire Electricity Board

DATE: 31/11/83

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Restriction (None on Manweb System)

REASON: Cable conductor terminations burnt to open circuit due to passage of fault current.

UPDATE:

REMEDIAL ACTION: Care required in jointing of terminations.