



1 SCOPE

This document details the application of SOP 27 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Lucy TRMU Mk2 11 kV R.M.U.

ORIGINATING REC: Northern Ireland Electricity Service

DATE: 8/12/83

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Restriction (None on Manweb System).

REASON: Operating handle could fit oil switch mechanism incorrectly, to give incomplete movement of switch blades.

UPDATE:

REMEDIAL ACTION: Longer pin fitted to handle.