



1 SCOPE

This document details the application of SOP 39 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Switchgear & Cowan RA4 & GEC RAE4 11 kV R.M.U.

ORIGINATING REC: MANWEB

DATE: 4/3/86

NO. INSTALLED IN MANWEB: 2400

NO. INSTALLED IN SCOTLAND:

STATUS: Live operation banned until modified.

REASON: After fitting 3 second delay device, some operating mechanisms jam on interlock lever.

UPDATE:

REMEDIAL ACTION: Modification required with unit dead. Check all operating sequences. See P.S.B. No. 27 and PSB 26.