



1 SCOPE

This document details the application of SOP 111 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Yorkshire SO-HI 11kV Range.

ORIGINATING REC: Yorkshire Electricity

DATE: 10/7/91

NO. INSTALLED IN MANWEB:0

NO. INSTALLED IN SCOTLAND:

STATUS: Access restricted. (None in Manweb)

REASON: Failure of busbar connection due to incorrect tightening.

UPDATE:

REMEDIAL ACTION: Inspection required.