



## 1 SCOPE

This document details the application of SOP 197 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** Switchgear & Cowans Type RA4 11kV RMU Ring Switches.  
Including types RAO4, RAE4, RA6, RAE6.

**ORIGINATING REC:** London Electric

**DATE:** 01/01/98

**NO. INSTALLED IN MANWEB:** 2400

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** No Restriction In Manweb. (See operational briefing note 2)

**REASON:**

RA4 Oil Switch in London Electric failed to close correctly when being operated from OFF to ON position. A discharge was heard from within the switch.

**UPDATE:**

**20.04.99:** Removal of partial operational restriction in London Electric following training of staff and inspection of suspect units.

**REMEDIAL ACTION:**