



1 SCOPE

This document details the application of SOP 198 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: REYROLLE ROKSS, ROSSS, ROK, ROS, RMS, RMK
11kV Oil switches, fuse switches and other ring main units

ORIGINATING REC: SCOTTISHPOWER

DATE: 11/02/98

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: **RESTRICTION:** The following restriction shall apply to all units of the above type.

No attempt shall be made to open the test access covers, fuse access covers or maintenance access covers whilst any part of the equipment is live.

REASON:

During routine work on a Reyrolle 11kV ring main unit when the cable test access cover on one of the ring switches was opened, a steel spacer barrel became detached from the cover bolt and fell through one of the test prod orifices into the main switch tank.

UPDATE:

REMEDIAL ACTION: