



1 SCOPE

This document details the application of SOP 208 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Reyrolle Type JS 11kV extensible oil switch

ORIGINATING REC: SCOTTISHPOWER

DATE: 13/08/98

NO. INSTALLED IN MANWEB: 0
NO. INSTALLED IN SCOTLAND:

STATUS: RESTRICTION.

No attempt shall be made to open the test access cover whilst any part of the equipment is live.

REASON:

It has been found possible to open the test access cover with the switch in the "ON" position.

UPDATE:

REMEDIAL ACTION:

Following an examination, with the equipment de-energised, if all the interlocks in the sub-station are found to be in good condition then the operational restriction may be removed from that sub-station. If any interlocks are found damaged then the switchgear is to be replaced at the earliest opportunity.