

# SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-236 **SOP 236**

Issue No. 1 October 2000

### 1 **SCOPE**

This document details the application of SOP 236 issued by the Electricity Association.

#### 2 **ISSUE RECORD**

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

<b>Issue Date</b>	Issue No	Author	<b>Amendment Details</b>
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

### **ISSUE AUTHORITY** 3

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



## SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-236 **SOP 236**

Issue No. 1 October 2000

### SOP DETAILS

**TYPE:** All 33kV Transformer cable boxes filled with G38 resin.

**ORIGINATING REC:** Northern Ireland Electric

**DATE:** 16/07/99

NO. INSTALLED IN MANWEB: NO. INSTALLED IN SCOTLAND:

**STATUS:** RESTRICTION. (Not applied in MANWEB).

The following restriction imposed by Northern Ireland Electric:

Work and/or testing in the vicinity of transformer cable end boxes shall be limited to essential operations only until all sites have been evaluated.

See DIN 99/32 and 99/49. **REASON:** 

**UPDATE:** 

**REMEDIAL ACTION:**