



1 SCOPE

This document details the application of SOP 240 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Connectors & Switchgear Type ADX2C 400kV adapter plate

ORIGINATING REC: NGC

DATE: 05/07/99

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Restriction (no equipment of this type on Manweb system)

The following restriction will be applied by NGC:

Access restricted in the vicinity of Busbars which are known to vibrate.

REASON:

Access restricted in the vicinity of vibrating busbars which are rigidly terminated and incorporating a Connectors & Switchgear type ADX2C adapter plate, due to the risk of adapter plate failure which may cause the busbar to fall to the ground.

UPDATE:

REMEDIAL ACTION:

Further action awaits the outcome of an investigation.