



1 SCOPE

This document details the application of SOP 261 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE : Brush type FV 11kV circuit breaker

ORIGINATING REC: Seeboard

DATE: 26/09/00

NO. INSTALLED IN MANWEB: None

NO. INSTALLED IN SCOTLAND:

STATUS:

Ban on local live operation of selector and circuit breaker.

No equipment of this type in Manweb.

REASON:

Restriction imposed following disruptive failure between busbar chamber and circuit breaker cubicle (DIN 2000/128 refers).

UPDATE:

REMEDIAL ACTION: