



1 SCOPE

This document details the application of SOP 262 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE : GEC BVRP500 11kV Oil Circuit Breaker

ORIGINATING REC : Manweb

DATE : 28/09/00

NO. INSTALLED IN MANWEB : Approx 80

STATUS : Restriction: **DO NOT OPERATE LIVE.**

NO ENTRY INTO SWITCHROOM FOR NON-ESSENTIAL WORK. IF IT IS SUSPECTED THAT ONE OF THE OCBs HAS OPERATED UNDER FAULT CONDITIONS – NO ENTRY INTO SWITCHROOM UNTIL THE SWITCHBOARD HAS BEEN MADE NOT LIVE

REASON:

Restriction imposed following a disruptive failure at Llysfaen Road primary substation (DIN 2000/130 refers).

UPDATE:

REMEDIAL ACTION:

To be advised.