



1 SCOPE

This document details the application of SOP 277 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
August 2002	1	David Naylor	Initial Issue 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
David Naylor Senior Project Engineer	Alastair Ferguson Section Head Engineering Support	Eric Leavy Engineering & Transmission Operations Manager



4 SOP DETAILS

TYPE : Statter type OD/SA switch

ORIGINATING REC : GPU Power

DATE : 12/09/01

NO. INSTALLED IN MANWEB: One (part of VL20D RMU)

STATUS : Restriction: Ban on live operation and restricted access to substation. This restriction already exists in Manweb under SOPs 93 and 109

REASON: Further disruptive failure of oil switch.

UPDATE:

REMEDIAL ACTION: Unit to be removed from service.