



1 SCOPE

This document details the application of SOP 282 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
August 2002	1	David Naylor	Initial Issue 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
David Naylor Senior Project Engineer	Alastair Ferguson Section Head Engineering Support	Eric Leavy Engineering & Transmission Operations Manager



4 SOP DETAILS

TYPE : Lucy 11kV type TRMU Mk2 TSU & TRMU

ORIGINATING REC : Western Power Distribution

DATE : 15/10/01

NO. INSTALLED IN MANWEB: None

STATUS : Ban: No live operation.

REASON: A Lucy TRMU Mk2 slow closed, despite having been fitted with modification FC, cam cover and latch assembly.

UPDATE:

REMEDIAL ACTION: To be reviewed following an investigation with the manufacturer.