

SUSPENSION OF OPERATIONAL PRACTICE SOP 316

OPSAF-16-316 Issue No. 1 September 2005

1. SCOPE

This document details the application of SOP 316 issued by Energy Networks Association

2. ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
September 2005	1	David Walker	Initial issue

3. ISSUE AUTHORITY

Author	Owner	Issue Authority
David Walker	Alastair Ferguson	Andy Huthwaite
Technical Support Engineer	Plant Engineering Manager	Engineering &
		Transmission Operations
		Manager



SOP DETAILS

4.

SUSPENSION OF OPERATIONAL PRACTICE SOP 316

OPSAF-16-316 Issue No. 1 September 2005

TYPE:	Switchgear & Cowans RA	6 11KV RMU			
ORIGINATING DN	NO: EDF Energy				
DATE:	19 th of August 2004				
	N POWER SYSTEMS NORTH: N POWER SYSTEMS SOUTH:	0 0			
STATUS:	No live operation of ring switches	3			
SPPS Application:	plication: No units of this type on the SP T&D network.				
REASON:	Discovery of a broken SRBP drive	e linkage.			
UPDATE:					
REMEDIAL ACTION:					