

1. SCOPE

This document details the application of SOP 318 issued by Energy Networks Association

2. ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
September 2005	1	David Walker	Initial issue

3. ISSUE AUTHORITY

Author	Owner	Issue Authority
David Walker Technical Support Engineer	Alastair Ferguson Plant Engineering Manager	Andy Huthwaite Engineering & Transmission Operations Manager

4. SOP DETAILS

TYPE: Brush Switchgear R4/1 Circuit breaker

ORIGINATING DNO: United Utilities

DATE: 20th of June 2005

NO. INSTALLED IN POWER SYSTEMS NORTH: 19

NO. INSTALLED IN POWER SYSTEMS SOUTH: 0

STATUS: Access Restrictions

SPPS Application:

REASON: Within a few minutes of an OCB operating to clear a fault in a CT chamber, a further flashover occurred on the busbar bushings of the OCB truck. The OCB truck and housing were severely damaged. **This SOP has been superseded.**

UPDATE: This SOP was withdrawn when SOP 321 was issued.

REMEDIAL ACTION: