



**1. SCOPE**

This document details the application of SOP 2010/0368/00 (Applicable to Long and Crawford Type GA switchfuses) issued by the Energy Networks Association.

**2. ISSUE RECORD**

This is a controlled maintained document.

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

<b>Issue Date</b>	<b>Issue No</b>	<b>Author</b>	<b>Amendment Details</b>
June 2010	1	Alan MacGregor	

**3. ISSUE AUTHORITY**

<b>Author</b>	<b>Owner</b>	<b>Issue Authority</b>
Alan MacGregor Lead Engineer Technical Risk	Alastair Ferguson Technical Risk Manager	Pearse Murray Asset Strategy and Network Programmes Director  .....



---

**4. SOP DETAILS**

**EQUIPMENT TYPE:** Long and Crawford Type GA switchfuses.

**ORIGINATING DNO** Central Networks

**DATE:** 28/5/2010

**NUMBER INSTALLED IN ENERGY NETWORKS NORTH:** 0

**NUMBER INSTALLED IN ENERGY NETWORKS SOUTH:** 0

**REASON:** Second disruptive failure of L&C GA switchfuse.

**STATUS IN INITIATING DNO:** Dead operations of the switchfuse only.

**SPEN APPLICATION:** No application. No units of this switchgear remain on the network.

**UPDATE:** N/A

**REMEDIAL ACTION:** N/A