

1. SCOPE

This document details the application of SOP 323 issued by Energy Networks Association

2. ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
September 2005	1	David Walker	Initial issue

3. ISSUE AUTHORITY

Author	Owner	Issue Authority
David Walker Technical Support Engineer	Alastair Ferguson Plant Engineering Manager	Andy Huthwaite Engineering & Transmission Operations Manager

4. SOP DETAILS

TYPE: GEC Alstom FX11 132KV Circuit breaker

ORIGINATING DNO: RWE Npower

DATE: 4th of April 2005

NO. INSTALLED IN POWER SYSTEMS NORTH: 7

NO. INSTALLED IN POWER SYSTEMS SOUTH: 1

STATUS: 7meter exclusion zone around Circuit breaker

SPPS Application: **It is not considered appropriate to apply this SOP to the SP T&D network, due to the event circumstances.**

REASON: The blue phase interrupter failed to clear following a suspected mal-synchronising of a generator circuit. The support porcelain of the blue phase interrupter chamber failed disruptively at some point following this event.

UPDATE:

REMEDIAL ACTION: